



WILSON NATIONAL LLC

A REAL ESTATE & AUCTION GROUP

Foamy Car Wash

Automatic:

- ◆ Needs computer tech to check out
- ◆ Bay 1-2 & 3 & 4 were all working order when I shut it down
- ◆ Bay 5 had an issue with either its switch or relay as machine ran
- ◆ Bay 3/4 vault needs replaced
- ◆ Bay 4 coin drop tube needs replaced
- ◆ Hanging furnace needs fan & checked out
- ◆ Some burst pipes need repair
- ◆ Bay 5 pump robbed to keep others going
- ◆ Pipes in attic may need repaired

Automatic Doors

- ◆ North door works
- ◆ South door needs work, relay maybe

I will help reinstall hoses & wands stored in shed

I have some extra parts if needed

Air compressor was good

Existing chemical stay with wash \$1000 or more